	21-Oct-16								
	REPORT OF NAVIGATION CHANNELS EP 1130-2-520								
COLUMBIA RIVER - OREGON & WASHINGTON					Minim	num depths i	n each 1/4 w	idth of	
MOUTH THROUGH PILLAR ROCK LOWER RANGE mile 25.2					channel entering from seaward				
		•							
					W1101				
					Mid-Channel				
Authorized Project					Left	Left	Right	Right	
NAME OF CHART	Date				Outside	Inside	Inside	Outside	
Name of Channel	of	Feet	Miles	Project	Quarter	Quarter	Quarter	Quarter	
(Mileage)	Survey	Width	Length	Depth	Feet	Feet	Feet	Feet	
MOUTH OF COLUMBIA RIVER	28-Sep-16								
Entrance Range **see note below		2000	3.3	55	59	59	56	**	
(-2.5 - 0.8)		640	3.3	48	**	**	**	46	
Sand Island Range **see note below		2000	2.2	55	54	55	54	**	
(0.8 - 3.0)		640	2.2	48	**	**	**	47	
LOWER DESDEMONA SANDS	21-Sep-16								
Lower Desdemona Sands	-	600	3.4	43	47	48	50	51	
(3.0 - 6.4)									
UPPER DESDEMONA SANDS	15-Aug-16								
Upper Desdemona Sands		600	3.6	43	43	44	43	41	
(6.4 - 10.0)									
FLAVEL BAR	30-Sep-16								
Tansy Point Turn & Range		600	3.6	43	42	44	45	35	
(10.0 -13.6)									
UPPER SANDS	1-Oct-16								
Tansy Point Turn & Range		600	1.2	43	41	44	45	42	
(13.6 - 14.8)									
Astoria Range		600	2.7	43	41	43	43	36	
(14.8 - 17.5)									
TONGUE POINT CROSSING	30-Sep-16								
Tongue Point Channel		600	2.2	43	40	43	44	44	
(17.5 - 19.7)									
Harrington Point Range		600	1.7	43	42	44	43	39	
(19.7 - 21.4)									
MILLER SANDS	6-Sep-16								
Harrington Point Range	,	600	0.9	43	39	43	44	39	
(21.4 - 22.3)									
Miller Sands Range		600	2.2	43	41	44	43	28	
(22.3 - 24.5)									
Pillar Rock Lower Range		600	0.7	43	39	44	44	40	
(24.5 - 25.2)									
\_ ·· <b></b> /		1				1	1	<u> </u>	

ENG Form 4020-R (Nov 1990)

Reference is Navigation Chart No. 18521.

Note: Controlling Depths in Channels Entering from Seaward in feet at Mean Lower Low Water from the Entrance to Harrington Point and Columbia River Datum above that point. \*\* Channel is 2640 feet wide with Right Outside Quarter (640 feet) maintained at only 48 feet depth.

Page 1

COLUMBIA RIVER CHANNEL DEPTHS
ENTRANCE TO MILLER SANDS RANGE
TABULATED FROM SURVEYS BY THE CORPS OF ENGINEERS - REPORT OF

21-Oct-16

Controlling Depths in Fee	Controlling Depths in Feet at MEAN LOWER LOW WATER (MLLW) * SEE FOOTNOTE						PROJECT DIMENSIONS		
	Left	Left	Right	Right	Date		Length		
NAME OF CHANNEL	Outside	Inside	Inside	Outside	of	Width	STAT	Depth	
	Quarter	Quarter	Quarter	Quarter	Survey	(Feet)	(Miles)	(Feet)	
Entrance Range **	59	59	56	**	28-Sep-16	2000	3.3	55	
	**	**	**	46	28-Sep-16	640	3.3	48	
Sand Island Range **	54	55	54	**	28-Sep-16	2000	2.2	55	
	**	**	**	47	28-Sep-16	640	2.2	48	
Lower Desdemona Sands	47	48	50	51	21-Sep-16	600	3.4	43	
Upper Desdemona Sands	43	44	43	41	15-Aug-16	600	3.6	43	
Tansy Point Turn & Range	41	44	45	35	1-Oct-16	600	4.8	43	
Astoria Range	41	43	43	36	1-Oct-16	600	2.7	43	
Tongue Point Channel	40	43	44	44	30-Sep-16	600	2.2	43	
Harrington Point Range	39	43	43	39	30-Sep-16	600	2.6	43	
Miller Sands Range * (CRD)	41	44	43	28	6-Sep-16	600	2.2	43	

<sup>\*</sup> Controlling Depths in Channels Entering from Seaward in feet at Mean Lower Low Water from the Entrance to Harrington Point and Columbia River Datum (CRD) above that point.

Reduce size to 80% of current size to print out to a size that matches tab boxes currently on NOAA charts.

For Controlling Depth Information, consult the Local Notice to Mariners and/or the following Portland District US Army Corps of Engineers website: http://www.nwp.usace.army.mil/Missions/Navigation.aspx Channel status reports

\*\* Channel width is 2640 feet with two controlling depths, northern width is 2000 feet and southern width is 640 feet